

MATERIAL SAFETY DATA SHEET

PRODUCT TRADE NAME:

HOMAX PRODUCTS, INC. STEEL WOOL

SECTION I - MANUFACTURER IDENTIFICATION

MANUFACTURER'S NAME: **24 HOUR EMERGENCY PHONE NUMBER**:

CHEMTREC

RHODES AMERICAN

1540 E. DUNDEE RD SUITE 210

PALATINE, IL 60623

INFORMATION PHONE NUMBER: 1-800-729-9029

1-800-424-9300

DATE OF PREPARATION: 06/30/03

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

NON HAZARDOUS STEEL 100%

INGREDIENTS

CAS # NIOSH (RTECS)

7439-89-6 N06925000 Fe – 98% Si - .35%

7440-44-0 FF580000 C - .7%-.14% 7439-96-5 009275000 Mn - .95%MAX. P - .08% MAX.

P - .08% MAX S - .05% MAX.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

APPEARANCE AND ODOR: GRAY FINE STEEL WOOL FIBER, NO ODOR

BOILING POINT: 2750 DEGREES C

VAPOR PRESSURE (MMHG/70F) N/A

MELTING POINT: 1535 DEGREES C

VAPOR DENSITY (AIR =1 N/A SPECIFIC GRAVITY (WATER=1) 7.8 EVAPORATION RATE N/A

SOLUBILITY IN WATER NOT SOLUBLE

SECTION IV - FIRE AND EXPLOSION DATA

FLASH POINT (METHOD USED): 250 DEGREES C

LEL: N/A UEL: N/A

N/A

EXTINGUISHING MEDIA: WATER/CARBON DIOXIDE

SPECIAL FIRE FIGHTING WEAR NIOSH/MSHA APPROVED SCBA AND FULL PROTECTIVE EQUIPMENT

PROCEDURES:

UNUSUAL FIRE AND EXPLOSION AVOID CONTACT WITH INCOMPATIBLE MATERIAL.

HAZARDS:

SECTION V - REACTIVITY DATA

STABILITY:

MATERIAL IS STABLE.

INCOMPATIBILITY (MATERIALS TO AVOID):

AVOID CONTACT WITH OPEN FLAMES & ELECTRICITY.

HAZARDOUS DECOMPOSITION PRODUCTS:

HYDROGEN IS FORMED WHEN IN CONTACT WITH MINERAL ACIDS.

HAZARDOUS POLYMERIZATION:

NO

CONDITIONS TO AVOID: (POLY)

NOT RELEVANT

SECTION VI – HEALTH HAZARD DATA

LD50-LC50 MIXTURE: NOT GIVEN FOR PRODUCT AS A WHOLE

ROUTE OF ENTRY: INHALATION: YES SKIN: NO INGESTION: YES

HEALTH HAZARDS ACUTE & CHRONIC: NONE APPLICABLE CARCINOGENICITY: NTP: NO IARC: NO OSHA: NO

EXPLANATION OF CARCINOGENICITY: CONTAINS NO INGREDIENTS THAT ARE CARCINOGENS OR SUSPECTED

CARCINOGENS

SIGNS/SYMPTOMS OF EXPOSURE: EYE IRRITATION

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: UPPER RESPIRATORY DISEASE. EMERGENCY/FIRST AID PROCEDURES: IRRIGATE EYES-CALL PHYSICIAN IMMEDIATELY

SECTION VII – PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN INCASE MATERIAL IS RELEASED OR SPILLED:

SWEEP UP MATERIAL FOR DISPOSAL. GLOVE RECOMMENDED.

WASTE DISPOSAL METHOD:

GENERAL BULD DISPOSAL METHOD.

PRECAUTIONSTO BE TAKEN IN HANDLING AND STORAGE:

USE PROTECTIVE GLOVES. STORE AWAY FROM OXIDIZING AGENTS & MINERAL ACIDS.

NEUTRALIZING AGENTS:

NONE

OTHER PRECAUTIONS:

NONE

SECTION VIII - CONTROL MEASURES

RESPIRATORY PROTECTION: NIOSH APPROVED DUST MASK.

VENTILATION: LOCAL EXHAUST

PROTECTIVE GLOVES: WORK GLOVES RESISTANT TO ABRASION.

EYE PROTECTION: GOGGLES RECOMMENDED

OTHER PROTECTIVE CLOTHING & EQUIPMENT: NONE

WORK HYGENIC PRACTICES: WASH WITH SOAP AND WATER AFTER HANDLING PRODUCT AND BEFORE EATING

& DRINKING

SUPPLIER SAFETY & HEALTH DATA: NONE

SECTION VIII- TRANSPORTATION DATA

DOT PSN CODE: NONE DOT PROPER SHIPPING NAME: NOT REGULATED

IMO PSN CODE: NONEIMO PROPER SHIPPING NAME: NOT REGULATEDIATA PSN CODE: NONEIATA PROPER SHIPPING NAME: NOT REGULATEDAFI PSN CODE: NONEAFI PROPER SHIPPING NAME: NOT REGULATED

DISPOSAL DATA: NONE

LABEL DATA: LABEL REQUIRED: YES

MFR LABEL: NONE LABEL STATUS: F

COMMON NAME: STEEL WOOL FIBERS SIGNAL WORD: CAUTION!

CHRONIC HAZARD: NO

ACUTE HEALTH HAZARD: NONE CONTACT HAZARD: NONE FIRE HAZARD: SLIGHT

REACTIVITY HAZARD: SLIGHT