

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing,
Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECTION I

MANUFACTURER'S NAME DURASOL CORPORATION		EMERGENCY TELEPHONE NO. 800 370-0683
ADDRESS (Number, Street, City, State and ZIP Code) 1 Oakland St. AMESBURY, MA. 01913		
CHEMICAL NAME AND SYNONYMS Blend of Calcium Carbonate & Bentonite	TRADE NAME AND SYNONYMS POUNCE	
CHEMICAL FAMILY	FORMULA Proprietary	

SECTION II - HAZARDOUS INGREDIENTS ** NONE **

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)
NONE **					

SECTION III - PHYSICAL DATA

BOILING POINT (°F.)	N/A	SPECIFIC GRAVITY (H ₂ O=1)	N/A
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT VOLATILE BY VOLUME (%)	N/A
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE (_____*)	N/A
SOLUBILITY IN WATER	Negligible		
APPEARANCE AND ODOR	Off-white powder, No odor		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used)	N/A	FLAMMABLE LIMITS	Lo	Hi
EXTINGUISHING MEDIA	Water			
SPECIAL FIRE FIGHTING PROCEDURES	NONE Necessary			
UNUSUAL FIRE AND EXPLOSION HAZARDS				

SECTION V - HEALTH HAZARD DATA NONE

THRESHOLD LIMIT VALUE

NONE

EFFECTS OF OVEREXPOSURE

Irritation in respiratory tract ONLY for severe over-exposure.

EMERGENCY AND FIRST AID PROCEDURES

Wash dust from skin with soap and water. Flush out EYES with generous amounts of water.

Not Applicable

SECTION VI - REACTIVITY DATA

NONE

STABILITY

UNSTABLE

CONDITIONS TO AVOID

NONE

STABLE

XX

INCOMPATIBILITY (Materials to avoid)

NONE

HAZARDOUS DECOMPOSITION PRODUCTS

NONE

HAZARDOUS
POLYMERIZATION

MAY OCCUR

CONDITIONS TO AVOID

NONE

WILL NOT OCCUR

XXX

NONE

SECTION VII - SPILL OR LEAK PROCEDURES

NONE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Normal clean-up procedures for dust. Vacuum cleaning is recommended.

WASTE DISPOSAL METHOD

No special precautions necessary.

none

SECTION VIII - SPECIAL PROTECTION INFORMATION

NONE

RESPIRATORY PROTECTION (Specify type)

VENTILATION

LOCAL EXHAUST

SPECIAL

MECHANICAL (General)

OTHER

PROTECTIVE GLOVES

EYE PROTECTION

OTHER PROTECTIVE EQUIPMENT

NONE

SECTION IX - SPECIAL PRECAUTIONS

NONE

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

OTHER PRECAUTIONS